Material Safety Data Sheet (Complies with 29 CFR 1910.1200)

Section I				
Manufacturer	Carlisle Brake & Fr	Carlisle Brake & Friction 920 Lake Road Medina, Ohio 44256		
Emergency Phone .	330-725-4941	Effective Date	February 12, 1997	
Chemical Name	Friction Material	Revision Date	March 17, 2003	
Tradename	Sintered Friction M	Sintered Friction Material		
Category	Inorganic829D			

Section II - Hazardous Ingredients / Identity				
Component	OSHA-PEL (mg/m ³⁾	ACGIH-TLV	%	CAS No.
		(mg/m^3)		
Copper	1.0	1.0	Proprietary	7440-50-8
Iron	Total=15.0 Resp.= 5.0	10.0	Proprietary	
Carbon	Total=15.0 Resp.= 5.0	10.0	Proprietary	7782-42-5
Mullite/ Glass	Resp.= 5.0	10.0		1302-93-8
				60676-86-0

Section III - Physical Characteristics			
Boiling Point	N/A	Sp.Gr. (H ₂ O=1)	5.1
Vapor Press (mm Hg)	N/A	Solubility in Water	Insoluble
Reactivity in Water	N/A	Vapor Density (Air=1)	N/A
Melting Point	> 1550° F	Color	Copper color
Appearance/Odor	No Odor		

Section IV - Fire and Explosion Data				
Flashpoint	N/A	Method used	N/A	
Flammable Limits (LEL/UEL)	N/A	Special Fire Fighting Prod	cial Fire Fighting Procedure None	
Auto Ignition Temperature	N/A	Extinguishing Media	CO ₂ , f	Foam, dry chemical, water
Unusual Fire and Explosion Hazards	None			

Section V - Reactivity Data		
Stability	Stable	
Incompatibility (Materials to Avoid)	None	
Hazardous Decomposition Products	None	
Hazardous Polymerization	Will Not Occur	
Conditions to Avoid	None	

Section VI - Health Hazards

Effects of Overexposure:

Inhalation: a) Inhalation of high concentrations of copper dust may cause intense sneezing, nausia,

weakness and fever. Can cause hemolysis of red blood cells, deposition of hemofuscin in the

liver and possible injury to lung cells.

b) Chronic exposure to carbon as graphite dust can cause fibrosis, emphysema and

corpulmonale.

c) Iron can cause coughing, slight upper respiratory irritation, and a metallic taste in the mouth.

Repeated exposure to copper (as salts) may cause dermatitis. If abrasions are present, lead

exposure could be significant.

Skin:

Emergency Procedures

Eye Contact: Copper may cause conjunctivitis or ulceration and turbidity of the cornea. In case of contact,

immediately flush with water for 15 minutes, including under the eyelids. Seek medical help

immediately if material cannot be adequately removed from the eye.

Skin Contact: Wash thoroughly with soap and water.

Inhalation: Following exposure to a large amount of dust, remove from exposure. If breathing has stopped,

perform artificial respiration. Contact a physician.

Ingestion: Unlikely. If ingestion occurs, contact a physician.

.Section VII - Spill/Leak Procedures		
Handling, Storage	None applicable	
DOT Shipping Rules	Non-hazardous as "article", no special precautions	
Spill/Leak	N/A	
Waste Disposal Methods	Check with local counsel for applicable laws/regulations. Lead is subject to SARA 313R reporting	

Section VIII - Special Protection /Control Measures		
Respiratory Protection/Ventilation	Use a NIOSH approved respirator with appropriate filters when exposed to brake wear products. Use exhaust ventilation to keep exposure below exposure limits.	
Protective Gloves	Recommended, particularly if sensitive skin.	
Eye Protection	Recommended	
Other Protective Equipment	N/A	

Section IX - Special Precautions

No special precautions necessary

Disclaimer

The information contained herein is based on data available at this time and is believed to be accurate. No warranty, however, is expressed or implied in no event will Carlisle Brake & Friction be liable for incidental or consequential damages of any kind regarding the accuracy of this data or the results to be obtained from the use thereof. Since information contained herein may be applied under conditions beyond our control and with which we may be unfamiliar, no responsibility is assumed for the results of its use. The person receiving this information should make his own determination of the suitability of the material for his particular purpose.